

BOISE CITY INVENTORY OF HISTORIC PLACES
Boise City Historic Preservation Commission, City Hall,
150 North Capitol Boulevard, Boise, Idaho 83702

Proposed North End Historic District:

Survey: North 9th Street Reconnaissance Survey

Inventory No. 169
 Date Completed: June 1992
 Photo(s): R3-#9
 State #: 01-17791
 Survey #: 178

1. Name

Historic:
and/or Common:

2. Location

Street Address: 818 Eastman

R3856000270

Subdivision: 6 5 1/2 Hyde Park Add.
 (Block(s)) Lot(s) Subdivision/Addition Name)

Township: SW $\frac{1}{4}$ of NE $\frac{1}{4}$ of NE $\frac{1}{4}$ of Sec 3 T3N R2E Boise Meridian
County: Ada

Map Reference: Boise North Quad 7.5 Series

UTM: Zone m E m N

Zoning Classification:

R-1C
 (At Site)

R-1C
 (Adjacent Properties)

3. Classification

Category

 District
X Building(s)
 Structure
 Site
 Object

Ownership

 Public
X Private
 Mixed

Original Use

 Agricultural
 Commercial
 Educational
 Government

 Industrial
 Military
 Museum
 Park

X Private Residence
 Multiple Occupancy
 Religious
 Other:

818

Present Use

<input type="checkbox"/> Agricultural	<input type="checkbox"/> Industrial	<input checked="" type="checkbox"/> Private Residence
<input type="checkbox"/> Commercial	<input type="checkbox"/> Military	<input type="checkbox"/> Multiple Occupancy
<input type="checkbox"/> Educational	<input type="checkbox"/> Museum	<input type="checkbox"/> Religious
<input type="checkbox"/> Government	<input type="checkbox"/> Park	<input type="checkbox"/> Other: _____

4. Current Owner of Property**Name:** Marion H. Horton**Address:** 988 E. State St., Eagle, ID 836165. Representation in Other Surveys/References**Survey Title:****National Register Status or Eligibility:** unevaluated**Determined by:** Cathy Sewell **Date Listed** _____

Contributing _____
Non-contributing _____

Published References:**Other:**6. Provenance and Description**Name of Original Owner:****Architect and/or Builder:****Date of Construction:** 1893-1903**Addition:****Condition**

☒ Excellent ☒ Good ☐ Fair ☐ Deteriorated ☐ Ruins
☐ Unexposed Remains **Comment:**

Status

☐ Unaltered ☒ Altered: **Date(s)** _____ **Unknown** ☒
☒ Original Site ☐ Moved: **Date(s)** _____

Comment:Description of Present and Original Appearance (if known)**Architectural Style:** Minimal Traditional?**Materials:** Aluminum siding

Comment: Poor-fair integrity (Eastman addition); storm windows; looks like it has had some changes (front facing Eastman could have been the addition, roof breaks there; includes garage structure

818

