

BOISE CITY INVENTORY OF HISTORIC PLACES

Inventory No. 084

Boise City Historic Preservation Commission
150 North Capitol Boulevard
Boise, Idaho 83702

Date Completed 4-1-89

Photo(s): R6-16

1. NAME

Historic: T.A. Blake House

and/or Common: Williamson Residence

2. LOCATION

Street Address: 1915 Harrison

Boise, ID 83702

Subdivision: 28 17 & 18 North Locust Grove Add.
(Block(s)) (Lot(s)) (Subdivision/Addition Name)

Zoning Classification: R-1C R-1C
(At Site) (Adjacent Properties)

3. CLASSIFICATION

<u>Category</u>	<u>Ownership</u>	<u>Status</u>
<input checked="" type="checkbox"/> District	<input type="checkbox"/> Public	<input checked="" type="checkbox"/> Occupied
<input type="checkbox"/> Building(s)	<input checked="" type="checkbox"/> Private	<input type="checkbox"/> Vacant
<input type="checkbox"/> Structure	<input type="checkbox"/> Mixed	<input type="checkbox"/> Work in Progress
<input type="checkbox"/> Site	<u>Public Acquisition</u>	<u>Accessibility</u>
<input type="checkbox"/> Object	<input type="checkbox"/> In Process	<input type="checkbox"/> Yes/Restricted
	<input type="checkbox"/> Being Considered	<input type="checkbox"/> Yes/Unrestricted
		<input type="checkbox"/> Not Accessible
 <u>Present Use</u>		
<input type="checkbox"/> Agriculture	<input type="checkbox"/> Industrial	<input checked="" type="checkbox"/> Private Residence
<input type="checkbox"/> Commercial	<input type="checkbox"/> Military	<input type="checkbox"/> Multiple Occupancy
<input type="checkbox"/> Educational	<input type="checkbox"/> Museum	<input type="checkbox"/> Religious
<input type="checkbox"/> Government	<input type="checkbox"/> Park	<input type="checkbox"/> Other: _____

4. CURRENT OWNER OF PROPERTY

Name: Samuel S. & Cheryl Williamson

Address: 1915 Harrison Blvd Boise Idaho 83702
(Number) (Street) (City) (State) (Zip)

5. REPRESENTATION IN OTHER SURVEYS/REFERENCES

Survey Title: Harrison Boulevard Historic District
National Register Inventory—29 Sept. 1979

National Register Status: (Date Nominated) 29 Feb 80 (Date Listed)

6. PROVENANCE AND DESCRIPTION

Name of Original Owner: J. A. Blake

Architect or Builder: Unknown

Date of Construction: 1923 Addition(s):

Condition

___ Excellent. ☒ Good. ___ Fair. ___ Deteriorated. ___ Ruins.
___ Unexposed Remains. Comment:

Status

___ Unaltered ☒ Altered: Date(s): Windows
☒ Original Site ___ Moved: Date(s):

Restoration Potential

☒ Excellent. ___ Good. ___ Fair. ___ Poor. ___ Infeasable.

Comment: Well kept.

Description of Present and Original Appearance (if known.)

Architectural Style: Cottage

Attached Check List of Exterior Features Completed: ☒ Yes ___ No

COMMENT:

The J. A. Blake residence, was built in 1923. This hipped roof cottage has an unusual window bay in front, which appears to be an alteration. There is a recessed left side entry, with paneled door and an entablature. Both sides have bay windows, and the shingles are in alternating wide and narrow horizontal bands.

12/86 Re-roofed.

7. SIGNIFICANCE

Inventory No. 084

HISTORICAL-CULTURAL-EDUCATIONAL

☐ Community Development. ☐ Cultural. ☐ Ethnic Group.
☐ Historic. ☐ Significant Person. ☐ Other. _____
☐ Art. ☐ Economic. ☐ Education. ☐ Exploration/
 Settlement. ☐ Military. ☐ Political. ☐ Religious.
☐ Scientific. ☐ Social. ☐ Other: _____
ARCHITECTURE-ENGINEERING
☐ Characteristic of Style. ☐ Distinctive/Outstanding Example.
☐ Innovative Feature. ☐ Rare/Unusual Feature. ☐ Rare Style.
☐ Work of Influential Designer. ☐ Other: _____

X GEOGRAPHIC

☒ * Distinctive Area/Neighborhood. ☐ Established/Prominent
 Feature. ☐ Historic/Cultural/Stylistic Theme Area.
 Other: _____

ARCHAEOLOGICAL

☐ Prehistoric. ☐ Historic. ☐ Other: _____

Statement of Significance: (Attach sheets as required.)

*See overall Statement of Significance for the District.

7a. STATUS: Non-contributing

8. Inventory prepared by: _____

W.D. Yennie

9. ACTION BY BOISE CITY

Date approved by Commission: _____






















































Chairman



























Date Approved: _____

Recommended for Boise City Designation: ☐ Historic Property/Landmark.
☐ Historical District. ☐ Historic Site. ☐ Other: _____

Date of Historic Preservation Commission Recommendations: _____

Approved by Boise City: Date: _____ Ordinance No. _____

1 STORIES				
				OTHER
1	1 1/2	2	2 1/2	
2 PLAN				
				
SQUARE	RECTANG.	O	L	U
				
T	H	POLY.	IRREG.	
3 BAYS				
1	2	3	4	5 OTHER
4 MATERIALS (PRIMARY)				
				
LOG-FULL DOVE-TAIL	LOG-HALF DOVE-TAIL	LOG-SADDLE NOTCH	LOG-LAP	LOG-STEPPED NOTCH
				
BOARD-BATTEN	CLAP-BOARD	SHIPLAP	COMPOSITION	SHINGLE
				
SANDSTONE DRESSED	SANDSTONE RUSTICATED	CONCRETE BLOCK	LAVA ROCK	TUFF
				OTHER
BRICK	STUCCO	ADOBE	ALUMINUM SIDING	
5 ADDITIONAL MATERIAL (SECONDARY)				
				
WOOD	TERRA-COTTA	PLASTER OR STUCCO	STONE	BRICK
				
METAL	SHINGLE	OTHER		
6 ROOF				
				
GABLE	ADDITIONAL GABLE-OFFSET	ADDITIONAL GABLE-CENTERED	STEPPED GABLE	PARAPET GABLE
				
HIP	TRUNCATED HIP	GAMBREL	MANSARD	SHED
			OTHER	
FLAT	DOMED	PYRAMID	OTHER	

7 DORMERS				
NUMBER:	FRONT	SIDE		
			GABLE	GABLE w/RETURN
				
PEDIMENT	SWEPT	HOODED	HIPPED	SHED
				
TRIANGULAR	MANSARD	PALLADIAN	ORNAMENTED	OTHER
8 ROOF TRIM				
				
CLOSE EAVES	OVERHANGING EAVES	BRACKETS	CORNICE	PARAPET
				
BALUSTRADED PARAPET	CUPOLA	CRENELLATED BATTLEMENT	BELVEDERE	FINIAL
				
CRESTING	GABLE RETURNS	FLARED	OTHER	

9 WINDOWS - HEAD												
FLAT ARCH	SEGMENTAL	ROUND	GOthic	TUDOR								
					OTHER							
ENTABLA-TURE	PEDIMENT	SEGMENTAL PEDIMENT	HOOD	KEYSTONE	OTHER							
10 MATERIAL - HEAD												
BRICK	STONE	METAL	WOOD	TERRA-COTTA								
11 WINDOWS - TYPE												
SINGLE SASH	DOUBLE HUNG SASH	TRANSOMS PLAIN	LEADED GLASS TRANSOM	WOODEN PATTERN TRANSOMS	CASEMENT							
SASH W/ SIDELIGHT	BAY SQUARED	ORIEL	PALLADIAN	QUEEN ANNE	OTHER							
12 NO. OF LIGHTS OR PANES												
UPPER SASH	1	2	3	4	5	6	7	8	9	10	11	12
LOWER SASH	1	2	3	4	5	6	7	8	9	10	11	12
13 MAIN ENTRY												
SINGLE DOOR	DOUBLE DOOR	LEADED GLASS	WINDOW IN DOOR	ORNAMENT-ED DOOR								
OUTSET	RECESSED	TRANSOM	SIDE PANELS	SIDE LIGHTS								
FANLIGHT	PILASTERS	PEDIMENT	ENTABLA-TURE	SEGMENT-ED PEDIME								

14 PORCHES				
	INSET	RUNS LENGTH OF PORCH	CENTERED	WRAP-AROUND
OPEN	CLOSED	REAR	SIDE	OTHER
PORTICO	OFFSET	DORIC COLUMNS	IONIC COLUMNS	CORIN-THIAN COLUMNS
TUSCAN COLUMNS	POSTS	BALUSTRADE	ARCADE	STOOP
15 ADDITIONAL FEATURES				
TOWER	BALCONY	ATTACHED GARAGE	SLEEPING SUNPORCH	2-STORY BAY
16 ADDITIONS				
1 STORY	1 1/2 STORY	2 STORY	2 1/2 STORY	TO REAR
TO LEFT SIDE	TO RIGHT SIDE	SAME MATERIAL	SAME STYLE	

