

IDAHO HISTORIC SITES INVENTORY FORM

PROPERTY NAME Greyhound Bus Station FIELD# BANNOCK W 1212

STREET 1212 W BANNOCK ST RESTRICT

CITY Boise VICINITY COUNTY CD 1 COUNTY NAME Ada

SUBNAME B C O T (BOISE CITY ORIGINAL) BLOCK 49 SUBLOT 1-6 ACRES 1 LESS THAN

TAX PARCEL R1013003246 UTMZ 11 EASTING 563975 NORTHING 4829981

TOWNSHIP 3 N_S N RANGE 2 E_W E SECTION 3 SE 1/4, 1/4 SW 1/4

QUADRANGLE BOISE SOUTH OTHERMAP

SANBORN MAP SANBORN MAP# PHOTO# Digital

PROPERTY TYPE Building CONST/ACT1 Original Construction ACTDATE1 1959 CIRCA1

CONST/ACT2 Alteration ACTDATE2 1978 CIRCA2

ASSOCIATED FEATURES bldg TOTAL # FEATURES 1

ORIGINAL USE Transportation WALL MATERIAL CERAMIC TILE

ORIGSUBUSE Road-related FOUND. MATERIAL CONCRETE

CURRENT USE Transportation ROOF MATERIAL

CURSUBUSE Road-related OTHER MATERIAL CONCRETE

ARCHSTYLE Other: Modern Movement PLAN Rectangular CONDITION Good

NR REF # NPS CERT ACTIONDATE FUTURE ELIG DATE

DIST/MPLNAME1 DIST/MPLNAME2

Individually Eligible Contributing in a potential district Noncontributing Future eligibility

Not Eligible Multiple Property Study Not evaluated

CRITERIA A B C D CRITERIA CONSIDERATION A B C D E F G

AREA OF SIGNIF Architecture AREA OF SIGNIF Transportation

COMMENTS This property possesses the following aspects of integrity: location, design, materials, workmanship, feeling, and association. The integrity of setting is compromised.

PROJ/RPT TITLE Urban Renewal District Survey SVY DATE 5/14/17 SVY LEVEL Reconnaissance

RECORDED BY Kerry Davis, PSLLC PH 816-225-5605 ADDRESS 1007 E. Jefferson Street, Boise, ID 83712

SUBMITTED PHOTOS NEGS SLIDES SKETCH MAP

SVY RPT # ***** FOR ISHPO USE ONLY ***** IHSI# URD-081

MS RPT # SITS#

IHPR # HABS NO. ID- HAER NO. ID- REV#

CS # IHSI# REF NR REF# 2 REV# REF

SVY RPT# 1 SVY RPT# 2 SVY RPT# 3 MS RPT# 1 MS RPT# 2

ADD'L NOTES

MORE DATA

ATTACH

OF PHOTOS NEGBOX# # OF SLIDES SHPO DETER DETER DATE

INITIALED ENTRY DATE REVISE REVISE REVISE

IHSI#	URD-081
SITS#	
REV#	

IDAHO HISTORIC SITES INVENTORY FORM

PROPERTY NAME IHSI#

FIELD# COUNTY NAME

OTHER NAME

COUNTY CD CITY VICINITY

UTM REF2 UTM REF3 UTM REF4

OTHER MATERIAL2 CULTAFFIL AGENCYCERT

SIGNIFDATE SIGNIFPERIOD SIGNIFPERSON

ARCH/BUILD ARCHPLANS TAXEASE TAXCERT

OWNERSHIP PROPOWN

MORE DATA ATTACH

DOCSOURCE

ADD'L NOTES

COMMENTS

PHOTO LOG IHSI# REF INITIALED DATEENTERED

SKETCH

IHSI#	SITS#	REV#

IDAHO HISTORIC SITES INVENTORY FORM

PROPERTY NAME IHSI#
FIELD# COUNTY NAME

COMMENTS:

This property possesses the following aspects of integrity: location, design, materials, workmanship, feeling, and association. The integrity of setting is compromised.

This building has historic associations with the midcentury commercial and transportation-related development of the west edge of downtown Boise. It retains most aspects of integrity. It would contribute to a surrounding historic district comprised of other largely one-story mid-century commercial/service buildings. It may be individually eligible though, per consultation with SHPO, sufficient significance would need to be substantiated with additional history and context development outside the scope of this project.

Location: This property has not been moved, and thus retains integrity of location.

Setting: Although some parts of the early- and mid-twentieth century neighborhood survive, the historic mixed-use setting has experienced considerable change during the last half-century. Boxy multi-story buildings and parking lots have replaced small, single-family dwellings, religious, commercial and light industrial properties of the early and mid-twentieth century. This sprawling boxy building is an example of that change, having replaced a row of small dwellings.

Design: Most elements of the property's original mid-century design are intact, including its subtly adorned modern style, sprawling rectangular form, one-story massing, and minimal fenestration. The building footprint has not changed.

Materials: The property retains its integrity of materials, including the concrete block and tile exterior, metal-sash windows, and inset metal storefront entrance with a metal awning.

Workmanship: Elements of workmanship are evident, particularly relating to the exterior claddings.

Feeling: The property's integrity of feeling is present in the cumulative effects of the property's location, design, materials and workmanship, conveying a sense of past time and place.


Association: The integrity of the building's association with what little remains of the surrounding early- and mid-20th century mixed-use neighborhood is present.

ATTACH

IHSI#	_____
SITS#	_____
REV#	_____














View N, June 2017



View E, June 2017

INSPECTION RECORD 17728 DATE 6-1-59
Western Greyhound Lines, Inc.
OWNER LOCATION 1212 Bannock
CONTRACTOR L. H. Krieger & Co. VALUE \$191,000.00
TYPE OF BLDG. masonry HEIGHT 1 and 2 story
AREA Sq. Ft. 9185 NEW REMODEL
OCCUPANCY bus depot with shop, storage and restaurant
REMARKS: Conc. found., boiler area basement, masonry
ext., steel deck and tectum roof plank, 10 rooms and
rest rooms, gas hot water heat, ins. ceiling, plastered
int. SEE PLANS
Comp JAN 15 1960 PLAN FILE 59 S



1956